



ଓଡ଼ିଶା ବିଦ୍ୟୁତ ଶକ୍ତି ସଂଚାରଣ ନିଗମ ଲିମିଟେଡ.

ODISHA POWER TRANSMISSION CORPORATION LTD.

O/O : G.M. (ELECT.) E.H.T. (O&M) CIRCLE, BURLA,

DIST: SAMBALPUR (ODISHA) 768017

CORRIGENDUM TO OPEN TENDER CALL NOTICE NO. BRL-29/2025-26

NO.- EHTM/BRL/ TENDER/ 1780

DATE: 06.11.2025

CORRIGENDUM

With reference to the open tender call notice No. BRL-29/2025-26, the EMD amount to be read as Rs. 8,403.00 and the list of materials as follows.

All other terms & conditions will remain constant.

N.B:- All subsequent addendums/ corrigendum to the tender shall be hosted in the OPTCL's official web site <http://www.optcl.co.in>.

Rita Bhoi
for General Manager (Elect.)
E.H.T. (O&M) Circle, Burla

CLAMP & CONNECTOR REQUIRED FOR KATAPALI GSS

Sl No.	Description of Item
1	85mm dia (OD) Pipe Bus to Twin Moose clamp
2	85mm dia (OD) Pipe Bus jointer clamp
3	85mm dia (OD) pipe Bus to isolator stud (40mm) clamp
4	85mm dia (OD) pipe Bus PI clamp
5	220kv Vertical stud (40mm) to twin Moose conductor
6	220kV Expansion Joint 85mm dia (OD) pipe Bus to Center Break Isolator Stud clamp (40mm stud size) (Bimetallic-1mm) Vertical Stud
7	220kV Expansion Joint 85mm dia (OD) pipe Bus to Current Transformer Stud clamp (40mm stud size) (Bimetallic-1mm) Horizontal Stud
8	220kV Expansion Joint 85mm dia (OD) pipe Bus to Circuit Breaker Pad Clamp
9	220kV Expansion Joint 114mm dia (OD) pipe Bus to Center Break Isolator Stud clamp (40mm stud size) (Bimetallic-1mm) Vertical Stud
10	220kV Expansion Joint 114mm dia (OD) pipe Bus to Current Transformer Stud clamp (40mm stud size) (Bimetallic-1mm) Horizontal Stud
11	220kV Expansion Joint 114mm dia (OD) pipe Bus to Circuit Breaker Pad Clamp
12	220kv Rigid Clamp CT stud (48mm) to 85mm Pipe Bus
13	Straight through clamp from Moose Conductor to 48MM Stud (Bimetallic-1mm)
14	Straight through clamp from Moose Conductor to 40MM Stud of CT stud (Bimetallic-1mm)
15	Straight through clamp from Zebra Conductor to 30MM Stud (Bimetallic-1mm)
16	33 KV CT stud clamp (Bimetallic straight through for 25 mm ²) to Zebra conductor
17	PG Clamp (ACSR Zebra to Zebra)/4bolted
18	PG Clamp (ACSR Zebra to Panther)/4bolted
19	T-Clamp (ACSR Moose Run-ACSR Moose Drop)/6bolted
20	T-Clamp (ACSR Zebra Run-ACSR Zebra Drop)/6bolted
21	T-Clamp (ACSR Panther Run-ACSR zebra Drop)/6bolted
22	Spacer T-Clamp (Twin Zebra Run-Zebra Drop)
23	220KV Center Break Isolator Male Contact (Copper part only)
24	220KV Center Break Isolator Female Contact (Copper part only)
25	160MVA ALSTOM Trf. Bushing Clamp (132kv -60mm)
26	40MVA Areva make Power Trf-III Bushing Clamp (33 KV Side clamp)
27	Pad clamp for SI to Zebra conductor
28	Pad clamp for SI to Moose conductor
29	Pad clamp for 132 kv LA (Zebra)
30	Pad clamp for 220 kv LA (Moose)
31	PI clamp for Zebra conductor (132 KV)
32	132 KV Straight Through clamp from CVT stud (Bimetallic-3mm) to Zebra Conductor

Rita Zhor
 for **General Manager (E.I.)**
OPTCL EHT (O&M) Circle, Burla

**Clamp and Connector required at 132/33KV Grid S/S
Sambalpur**

SL No.	Description of Item
1	Spacer T clamp for twin ACSR Zebra (4 bolted)
2	Spacer clamp for twin ACSR Zebra (2 bolted)
3	T clamp for ACSR Panther run to Zebra drop (12 bolted)
4	12 X 65 mm G.I Nut- Bolt full thread
5	12 X 85 mm G.I Nut- Bolt full thread
6	08 X 65 mm G.I Nut- Bolt full thread
7	Flat Washer 12 mm
8	spring Washer 12 mm

Rita Bhoi
General Manager (El.)
for **OPTCL EHT (O&M) Circle, Burla**

**Clamp and Connector required at 132/33KV Grid S/S
Maneswar**

SL No.	Description of Item
1	Bimetallic CT Stud clamp for Moose Conductor (8 bolted)
2	Spacer clamp for twin ACSR Moose (2 bolted)
3	PI clamp for Moose conductor
4	132 KV Isolator Pad clamp (4 bolted) suitable for holding ACSR Moose conductor
5	PG clamp for ACSR Panther to ACSR Panther (3 bolted)
6	PG clamp for ACSR Panther to ACSR Panther (2 bolted)
7	T clamp for ACSR Pather run Moose drop

Rita Bhoi
General Manager (Et.)
for **OPTCL EHT (O&M) Circle, Burla**

**Clamp and Connector required at 132/33KV Grid S/S
Rairakhol.**

SL No.	Description of Item
1	Bimetallic CT Stud clamp for Zebra Conductor (8 bolted)
2	132 KV Isolator Pad clamp (4 bolted) suitable for holding ACSR Zebra conductor
3	Bimetallic T clamp for 132 KV Bushing for 132/33 KV, 12.5 MVA Transformer(6 bolted)
4	Bimetallic T clamp for 33 KV Bushing for 132/33 KV, 12.5 MVA Transformer(6 bolted)
5	T clamp for ACSR Zebra run to Zebra drop(12 bolted)
6	Dead end pipe along with hardware for ACSR Zebra
7	PG clamp for ACSR Zebra to ACSR Panther (4 bolted)
8	12 X 65 mm G.I Nut- Bolt full thread
9	12 X 85 mm G.I Nut- Bolt full thread
10	Flat Washer 12 mm
11	spring Washer 12 mm

Rita Bhor
for **General Manager (E.)**
OPTCL EHT (O&M) Circle, Burla